


1 2 3 4

\* DIMENSIONS MAY VARY IN ACTUAL INSTALLATION - FABRICATION CHANGES RESERVED - FIELD MEASUREMENT MAY BE REQUIRED \*


CORRECT  
INSTALLATION




INCORRECT  
INSTALLATION



CORRECTLY  
INSTALLED CENTER  
ROTOR SECTION



INCORRECTLY  
INSTALLED CENTER  
ROTOR SECTION



AUTHORIZED SIGNATURE: \_\_\_\_\_ DATE: \_\_\_ / \_\_\_ / \_\_\_

FIRST DRAWN	BY
01/23/19	CP
REVISED	BY
01/23/19	.

**www.TURNSTILES.us**  
 8641 South Warhawk Rd. Conifer, CO 80433  
 Patrick McAllister Tel: 303-670-1099

Equipment Location Detail	
Full Height Single Turnstile	
DWG	Correct Vs Incorrect Center Rotor Section Installation
DATE	01/23/19
SCALE =	< >
SHEET - 1 OF 1	